

Preserving Heritage: The Maintenance of National Heritage Anglican Churches in Malaysia

Editor:

Shirley Jin Lin Chua¹, Azlan Shah Ali², Wee Phong Ow³


Email:

shirleychua88@um.edu.my¹, asafab@um.edu.my²,
pt@uthm.edu.my³

Abstract: This book is a journey through time and space, through ornate arches and intricately carved pews, and through the hearts of those who have tirelessly ensured the conservation of these Anglican churches. It is a testament to the unwavering faith that binds communities and transcends the boundaries of time and culture. As the custodians of this cultural and spiritual legacy, it is with great pride and reverence that we present this book. It serves as an exploration of the intricate fusion of faith and heritage, offering a window into the soul of Malaysia. Through these pages, we invite you to embark on a journey of discovery, understanding, and appreciation for the monumental task of preserving our national heritage.

We are deeply grateful to the Malaysian Department of National Heritage, architects, custodians, conservators, historians, volunteers, and all those who have generously shared their knowledge and experiences to make this project possible. Without their dedication, this book would remain an unfulfilled dream. May the pages that follow inspire an enduring commitment to the maintenance and preservation of our National Heritage Anglican Churches, ensuring that they stand as timeless symbols of faith, culture, and history for generations to come.

Keywords: Heritage, churches, cultural, maintenance



Preserving Heritage:

The Maintenance of National Heritage

Anglican Churches

in Malaysia



Shirley Jin lin Chua
Azlan Shah Ali
Wee Phong Ow



Penerbit
UTHM

Preserving Heritage:

The Maintenance of National Heritage

Anglican Churches

in Malaysia

Preserving Heritage:

The Maintenance of National Heritage

Anglican Churches

in Malaysia

Shirley Jin Lin Chua
Azlan Shah Ali
Wee Phong Ow



© Penerbit UTHM
First Published 2025

Copyright reserved. Reproduction of any articles, illustrations and content of this book in any form be it electronic, mechanical photocopy, recording or any other form without any prior written permission from The Publisher's Office of Universiti Tun Hussein Onn Malaysia, Parit Raja, Batu Pahat, Johor is prohibited. Any negotiations are subjected to calculations of royalty and honorarium.

Authors: Shirley Jin Lin Chua, Azlan Shah Ali, Wee Phong Ow

Published by:

Penerbit UTHM
Universiti Tun Hussein Onn Malaysia
86400 Parit Raja,
Batu Pahat, Johor

Tel: 07-453 7051 / 7454
Fax: 07-453 6145

Website: <http://penerbit.uthm.edu.my>
E-mail: pemasaran.uthm@gmail.com
<http://e-bookstore.uthm.edu.my>

Penerbit UTHM is a member of
Majlis Penerbitan Ilmiah Malaysia (MAPIM)

Printed by:

ATTIN PRESS SDN. BHD.
No.8, Jalan Perindustrian PP4, Taman Perindustrian
Putra Permai, Bandar Putra Permai, 43300 Seri Kembangan, Selangor.
Tel: 03-8939 0660
Fax: 03-8939 9355
Email: attinpress@gmsil.com



Cataloguing-in-Publication Data

Perpustakaan Negara Malaysia

A catalogue record for this book is available
from the National Library of Malaysia

ISBN 978-629-490-169-8

Table of Contents

<i>List of Tables</i>	ix
<i>List of Figures</i>	xi
<i>Dedication</i>	xv
<i>Preface</i>	xvii

Chapter 1 Anglican Churches

1.1 Introduction	1
1.2 History of Anglican Churches in Malaysia	3
1.3 Typical Layout of a Church	4
1.3.1 Natrhex	5
1.3.2 Nave	5
1.3.3 Crossing	6
1.3.4 Transept	6
1.3.5 Chancel	6
1.4 Churches as Assets	6
1.5 The Malaysian Acts on Maintaining National Heritage	8
1.5.1 National Heritage Act 2005	9
1.5.2 Street, Damage and Building Act 1974	10
1.6 Guidelines on Maintaining Churches	12
1.7 Summary	12

Chapter 2 Building Components and Elements of Anglican Churches

2.1	Introduction	15
2.2	Architectural & Civil	18
2.2.1	Structure	18
2.2.1.1	Floor	19
2.2.1.2	Column	19
2.2.2	Exterior Enclosure	20
2.2.2.1	Wall and Painting	21
2.2.2.2	Window	22
2.2.2.3	Door	24
2.2.3	Ceiling & Roof	25
2.3	Electrical	27
2.3.1	Lighting	27
2.3.2	Audio-Visual	28
2.3.4	Ceiling Fan	28
2.3.5	Electrical Wiring	29
2.4	Mechanical	29
2.4.2	HVAC Systems	30
2.5	Summary	30

Chapter 3 The Defects of National Heritage Anglican Churches in Malaysia

3.1	Introduction	31
3.2	All Saints' Church, Taiping	32
3.2.1	Architectural & Civil	33
3.2.2	Electrical	45
3.3	Christ Church Melaka, Melaka	51
3.3.1	Architectural & Civil	53
3.3.2	Electrical	61
3.3.3	Mechanical	67
3.4	St. George's Anglican Church, Penang	69
3.4.1	Architectural & Civil	70
3.4.2	Electrical	77

3.4.3 Mechanical	80
3.5 St. Mary's Cathedral, Kuala Lumpur	82
3.5.1 Architectural & Civil	83
3.5.2 Electrical	91
3.5.3 Mechanical	96
3.6 Defects found at the churches	97
3.7 Summary	111
Chapter 4 Building Maintenance for Anglican Churches	
4.1 Introduction	113
4.2 The Current Maintenance of National Heritage Anglican Churches	113
4.3 Maintenance Theory of Reliability	116
4.4 Maintenance of Archirectural & Civil Components	118
4.4.1 Maintenance of Structure	118
4.4.2 Maintenance of Floor	122
4.4.3 Maintenance of Column	123
4.4.4 Maintenance of Exterior Enclosure	125
4.4.5 Maintenance of Wall and Painting	125
4.4.6 Maintenance of Window	127
4.4.7 Maintenance of Door	128
4.4.8 Maintenance of Ceiling & Roof	129
4.5 Maintenance of Electrical Components	130
4.5.1 Maintenance of Lighting	130
4.5.2 Maintenance of Audio-Visual Equipment	131
4.5.3 Maintenance of Ceiling Fan	132
4.5.4 Maintenance of Electrical Wiring	133
4.6 Maintenance of Mechanical Components	134
4.6.1 Maintenance of HVAC Systems	153
4.7 Summary	
Chapter 5 Maintenance Model for Anglican Churches	
5.1 Introduction	155
5.2 Maintenance Model for Anglican Churches in Malaysia	156

5.3 Contribution of the Maintenance Model for Anglican Churches	183
5.4 Summary	184
Chapter 6 Conclusion and Way Forward	
6.1 Conclusion	187
6.2 Way Forward	189
<i>Bibliography</i>	191
<i>Biography</i>	205
<i>Index</i>	209

List of Tables

Table 3.1	Building profile of All Saints' Church	33
Table 3.2	Building profile of Christ Church Melaka	52
Table 3.3	Building profile of St. George's Church	69
Table 3.4	Building profile of St. Mary's Cathedral	82
Table 3.5	Defects of surveyed churches according to their materials	103
Table 4.1	Compilation of maintenance actions from literature review for Anglican churches	136
Table 5.1	The computation of the decomposed weight of building disciplines within a church	158
Table 5.2	Proposed maintenance model for Anglican churches in Malaysia	160
Table 5.3	Proposed priority hierarchy of space type for maintenance at Anglican churches in Malaysia	183
Table 5.4	Proposed priority hierarchy of building components for maintenance at Anglican churches in Malaysia	183

List of Figures

Figure 1.1	Schematic Plan of a Church	5
Figure 2.1	Example of lancet windows	23
Figure 2.2	The Romanesque Church Portal	25
Figure 2.3	Hammer-beam roof of Westminster Hall	27
Figure 3.1	All Saints' Church	32
Figure 3.2	The newer-built church	33
Figure 3.3	Terrazzo and Ceramic tiles at All Saints' Church	34
Figure 3.4	Split and Stains on one of the columns at All Saint's Church	35
Figure 3.5	Peeling paints on the façade wall of Saints' Church	36
Figure 3.6	Decayed plank on the façade wall	37
Figure 3.7	Transom window at All Saints' Church	38
Figure 3.8	Lancet windows All Saints' Church	39
Figure 3.9	Stained-glass windows and crack of individual pane	40
Figure 3.10	Star crack of individual pane	40
Figure 3.11	Cracking of joints	40
Figure 3.12	Rose window of All Saints' Church	41
Figure 3.13	Casement windows at All Saints' Church	42
Figure 3.14	Two-shuttered wooden door with corroded flush bolt at the main entrance	43

Figure 3.15	The patch on the doors at south transept	44
Figure 3.16	Bottom rail had been patched up with different coloured plank	44
Figure 3.17	Stains found on Hammer-beam roof at All Saints' Church	45
Figure 3.18	Lighting found at All Saints' Church	46
Figure 3.19	Mic-stand mount without the equipment and missing light bulb	47
Figure 3.20	Light bulbs for exterior setting and projector removed	48
Figure 3.21	Ceiling fan along the nave	49
Figure 3.22	Double insulated cables that negatively affecting the aesthetics	50
Figure 3.23	Electrical sockets and The wall box at electricity meter had corroded	51
Figure 3.24	Christ Church Melaka	51
Figure 3.25	Flooring at Christ Church Melaka	54
Figure 3.26	Column currently under fungicidal attack	55
Figure 3.27	Defects found on the wall and skirting	56
Figure 3.28	Paint touch-up and Crating paint affecting the overall aesthetics	57
Figure 3.29	Stained-glass windows as replacements of the original windows	58
Figure 3.30	Doors with defects at Christ Church Melaka	59
Figure 3.31	Triple-layered doors on each of the aisles	60
Figure 3.32	Ceiling and roof of Christ Church Melaka	61
Figure 3.33	Lightings of Christ Church Melaka	62
Figure 3.34	Audio-visual system of Christ Church Melaka	64
Figure 3.35	Cable conduits neatly installed around the church	65
Figure 3.36	Distribution board, adjacent electrical equipment and switches at the church	66

Figure 3.37	Wall-mounted fans installed at Christ Church Melaka	67
Figure 3.38	Air conditioner and ductwork well-orderedly installed	68
Figure 3.39	St. George's Church, Penang	69
Figure 3.40	Terrazzo tiles and carpet at St. George's Church	72
Figure 3.41	Doric columns at St. George's Church	73
Figure 3.42	Rising damp started to appear again on the walls	74
Figure 3.43	Wooden louver windows at the portico of St. George's Church	75
Figure 3.44	Casement windows at the sanctuary of St. George's Church	75
Figure 3.45	Wooden door at St. George's Church	76
Figure 3.46	Ceiling and roof at St. George's Church	77
Figure 3.47	Lighting at St. George's Church	78
Figure 3.48	Electrical room at St. George's Church	79
Figure 3.49	Ceiling fans at St. George's Church	80
Figure 3.50	Air conditioner at St. George's Church	81
Figure 3.51	St. Mary's Cathedral	82
Figure 3.52	Defects found on the floor	85
Figure 3.53	Water stain found in St. Mary's Cathedral	86
Figure 3.54	Water stain with mould appearing on the façade wall	87
Figure 3.55	The stained-glass lancet windows at the sanctuary	88
Figure 3.56	Transom and Stained-glass lancet windows at St. Mary's Cathedral	88
Figure 3.57	Stained-glass lancet and Jalousie windows at St. Mary's Cathedral	89
Figure 3.58	Doors at St. Mary's Cathedral	90

Figure 3.59	Roof tiles and Hammer-beam roof at Hammer-beam roof at St. Mary's Cathedral	91
Figure 3.60	Lights at the external of St. Mary's Cathedral	92
Figure 3.61	Lighting at St. Mary's Cathedral	93
Figure 3.62	Audio-visual system at St. Mary's Cathedral	94
Figure 3.63	Conduits found at St. Mary's Cathedral	95
Figure 3.64	Ceiling fan and CCTV at Ceiling fan at St. Mary's Cathedral	96
Figure 3.65	Air conditioner at St. Mary's Cathedral	97
Figure 5.1	Decomposed weight of building discipline within a church	157
Figure 5.2	Comparison of building components in relation to each building discipline	157
Figure 5.3	Comparison of building disciplines in relation to each building component	159

Preface

In the midst of the vibrant tapestry of Malaysia's cultural heritage, there stand towering monuments of faith, history, and architectural grandeur—our National Heritage Anglican Churches. These sacred structures have been witnesses to centuries of change, silently echoing the stories of those who have gathered within their hallowed walls.

“Preserving Heritage: The Maintenance of National Heritage Anglican Churches in Malaysia” is not merely a book; it is a testament to the dedication, passion, and collective endeavour of countless individuals and organizations who have committed themselves to preserving the sanctity of these remarkable places of worship. Their work is a labour of love, a bridge between the past and the future, and a manifestation of our shared commitment to preserving our national heritage.

This book is a journey through time and space, through ornate arches and intricately carved pews, and through the hearts of those who have tirelessly ensured the conservation of these Anglican churches. It is a testament to the unwavering faith that binds communities and transcends the boundaries of time and culture. As the custodians of this cultural and spiritual legacy, it is with great pride and reverence that we present this book. It serves as an exploration of the intricate fusion of faith and heritage, offering a window into the soul of Malaysia. Through these pages, we invite you to embark on a journey

of discovery, understanding, and appreciation for the monumental task of preserving our national heritage.

We are deeply grateful to the Malaysian Department of National Heritage, architects, custodians, conservators, historians, volunteers, and all those who have generously shared their knowledge and experiences to make this project possible. Without their dedication, this book would remain an unfulfilled dream. May the pages that follow inspire an enduring commitment to the maintenance and preservation of our National Heritage Anglican Churches, ensuring that they stand as timeless symbols of faith, culture, and history for generations to come.



1

Anglican Churches

1.1 Introduction

A wide range of architectural styles and historical structures that contribute to the nation's identity. The country's rich cultural and historical influences, rooted in its multicultural community, have left a significant mark on its built environment. Beyond their spiritual importance, places of worship play a central role in the lives of many, spanning generations. Given the economic value of tourism, maintaining these places of worship is crucial. David (2017) emphasizes the importance of preserving prominent religious sites, noting their status as major tourist attractions. Neglecting their upkeep could significantly impact a country's revenue. Visitors are drawn to these sites not only for their spiritual significance but also for their historical, cultural, and aesthetic uniqueness, including distinctive architecture.

The term "Church," originating from the Old English word 'cirice,' refers to a place where Christians gather for worship. Hurlbut (1967) observes that in ancient times, up until the end of the second century, Christians primarily held their worship services in private homes, remote areas, at the graves of martyrs, and in the crypts of catacombs. Due to the difficult conditions of that era, characterized by poverty, oppression, and lawlessness, Christians would gather whenever and wherever they could.

Christian assemblies for worship often take place in a larger common area. Hurlbut (1967) further noted that these activities typically

1



2

Building Components and Elements of Anglican Churches

2.1 Introduction

Older buildings throughout Malaysia form an essential part of the National Heritage stock. Structures built between 1800 and 1948, which are gazetted as Heritage Buildings under the National Heritage Act 2005, are commonly referred to in Malaysia as “Pre-war Buildings” (Baharuddin et al., 2014). Examples of Pre-war Buildings include mosques, churches, post offices, and shop houses. As most of these structures were constructed before Malayan Independence, the design and technology used primarily reflect the influence of colonial architects. For example, St. George’s Church in Penang (1818) was designed by William Petrie, a British officer of the East India Company, and Sultan Abdul Samad Jamek Mosque (1909) was the work of Arthur Benison Hubback, an English architect and soldier. Consequently, it is not surprising that one of the significant challenges faced by these Pre-war Buildings is the lack of technical expertise needed for their maintenance and repair (Baharuddin et al., 2014). Furthermore, a report by Babulal (2019), highlights that the River of Life project, intended as a city beautification initiative by the Malaysian Government, inadvertently created an unfavourable environment for older buildings across the Klang Valley, ultimately worsening their performance deterioration.

Performance deterioration is inevitable for all building components, primarily due to aging, wear and tear, and external factors (Straub, 2009). Since performance loss is often reflected in identified defects,



3

The Defects of National Heritage Anglican Churches in Malaysia

3.1 Introduction

The authors sourced the list of National Heritage sites in Malaysia from the Department of National Heritage. The focus on National Heritage structures was intentional, as these buildings are recognized for their significant value to the nation. Upon reviewing the list, it was found that all the National Heritage churches listed were Anglican churches. Consequently, the four Anglican churches in Malaysia were selected to investigate on their defects and the current maintenance practices in place. The intention is to develop a maintenance framework to create awareness on maintenance of these National heritage churches.

The authors visited each of the four churches to gather essential information. This information has been compiled and is presented in the following sections, listed in alphabetical order:

- i. All Saints' Church, Taiping
- ii. Christ Church Melaka, Melaka
- iii. St. George's Church, Penang
- iv. St. Mary's Cathedral, Kuala Lumpur



4

Building Maintenance for Anglican Churches

4.1 Introduction

Building maintenance refers to the analysis of maintenance requirements associated with various building structures, elements and the assets contained within them (IWFM, 2018). It involves developing maintenance programmes by evaluating building usage, services, and control systems. This process does not end with the creation of these programmes but extends to managing and monitoring them. Furthermore, building maintenance encompasses the assessment and application of various management systems and technologies to prolong the life cycle of a building, while minimizing unnecessary deterioration (Peng, 2013).

4.2 The Current Maintenance of National Heritage Anglican Churches in Malaysia

The maintenance of Anglican churches in Malaysia faces significant challenges. Most notably, there is a general absence of comprehensive maintenance plans. For the four Anglican churches in Malaysia discussed in Chapter 3, St. George's Church has developed such a maintenance plan, but it remains under revision, and efforts to obtain the outdated version from the building custodian have been unsuccessful. This situation reflects a broader trend in Malaysia, where maintenance awareness is low, and building owners often adopt a reactive approach, addressing only those issues that directly impact users. Such a strategy, focused solely on corrective measures,



5

Maintenance Model for Anglican Churches

5.1 Introduction

To develop a maintenance model for Anglican churches, a questionnaire survey was conducted with experts in facilities management to gather their professional opinions on the significance of various spaces within a church, as well as the importance of specific disciplines associated with each space type. By identifying the relative importance of each element, this research aimed to provide critical insights for prioritizing maintenance tasks. The survey methodology utilized both the Analytic Hierarchy Process (AHP) and the Analytical Network Process (ANP), two well-established techniques in multi-criteria decision analysis.

The 32 respondents who passed the screening process were confirmed to have appropriate expertise or knowledge in the field. The majority of respondents were architects, followed by asset/facility management consultants and maintenance managers—professions highly specialized in construction and building management, often requiring advanced education. Given their roles, these professionals are frequently involved in decision-making processes related to building maintenance, and their responses are assumed to be credible, accurate, and unbiased. The educational backgrounds of the respondents were well-distributed across various professions in the construction industry, ensuring a comprehensive perspective in the study's findings.



6

Conclusion and Way Forward

6.1 Conclusion

This book revolves several key topics that collectively contribute to the development of a maintenance model for Anglican churches. These topics include an overview of Anglican churches, their historical context in Malaysia, typical church layouts, relevant Malaysian legislation concerning church maintenance, and the various building components and elements of Anglican churches. The narrative begins with an investigation into the maintenance of National Heritage Anglican churches in Malaysia, aiming to assess the building portfolio, identify defects, and evaluate the current maintenance practices in place.

Most of these churches lack a formal maintenance plan. While St. George's Church does have a maintenance plan, it is still undergoing revisions. Building owners typically address only what is visibly broken and has an immediate impact on users, relying predominantly on corrective maintenance. This situation is compounded by the absence of a comprehensive maintenance plan and, more critically, a properly trained maintenance team. The most significant challenges faced in preserving Anglican churches in Malaysia include budget constraints, accessibility issues and aesthetic considerations. All custodians identified budgeting as a major challenge. Even St. George's Church, which received support from the Department of National Heritage Malaysia, struggled with funding. For churches relying solely on congregational donations, sustaining maintenance

Bibliography

- Adventist Risk Management. (2011). *Church preventive maintenance schedules*.
- Ahluwalia, S. S. (2008). *A framework for efficient condition assessment of the building infrastructure* University of Waterloo]. Waterloo.
- Ahmad, A. G. B. (1993). *Conservation of British colonial buildings built between 1800 and 1930 in Malaysia* University of Sheffield]. Sheffield.
- Almodovar-Melendo, J., Cabeza-Lainez, J., & Rodriguez-Cunill, I. (2018). Lighting features in historical buildings: scientific analysis of the Church of Saint Louis of the Frenchmen in Sevilla. *Sustainability*, 10(3352), 1-23.
- Babulal, V. (2019). *River of Life project has fallen short of objectives*. New Straits Times. Retrieved June 9, 2019 from <https://www.nst.com.my/news/nation/2019/10/527674/river-life-project-has-fallen-short-objectives>
- Baharuddin, M. N., Bahardin, N. F., Rashid, R. A., Hashim, H., & Ali, I. M. (2014). *Analysis of critical factors and difficulties in maintaining historical building - a current implementation* MATEC Web of Conferences, Perak.
- Barton, A. D. (2000). Accounting for public heritage facilities - assets or liabilities of the government? *Accounting, Auditing &*

- Accountability Journal*, 13(2), 219-235.
- BBC. (2020). *Features of churches*. Retrieved 18.6 from <https://www.bbc.co.uk/bitesize/guides/zsgbtv4/revision/4>
- Bearg, D. W. (1993). *Indoor air quality and HVAC systems*. CRC Press.
- Beech, R. (2016). The hammer-beam roof of Westminster Hall and the structural rationale of Hugh Herland. *Architectural History*, 59, 25-61.
- Beskhyroun, S., Maghoub, G., El-Rifai, I., Mahgoub, H., Osticioli, I., Nevin, A., & El-naggar, A. (2019). Study of the painted dome of the Church of Archangel Gabriel, Cairo. *Egyptian Journal of Archaeological and Restoration Studies*, 9(2), 129-140.
- Bhavikatti, S. S. (1995). *Building construction*. Vikas Publishing House Pvt Ltd.
- Boethius, A. (1962). Of Tuscan columns. *American Journal of Archaeology*, 66(3), 249-254.
- Booth, J. (2012). *Interpreting churches: how the belief of a worshipping community is reflected throughout a church building*. [https://www.nationalchurchestrust.org/sites/default/files/resources/NWMFTA](https://www.nationalchurchestrust.org/sites/default/files/resources/NWMFTA_interpreting_churches_2012_0.pdf) interpreting churches 2012_0.pdf
- Brick Industry Association. (2017). *Maintenance of brick masonry* (Technical notes on brick construction, Issue. B. I. Association.
- Britannica. (2020). *Transept*. Retrieved June 9, 2019 from <https://www.britannica.com/technology/transept>
- Brocken, H., & Nijland, T. G. (2004). White efflorescence on brick masonry and concrete masonry blocks, with special emphasis on sulfate efflorescence on concrete blocks. *Construction and Building Materials*, 18, 315-323.
- Cannon, J. (2014). *Medieval church architecture*. Shire Publications.

- Carro, K. (2020). *Our ceiling fan maintenance tips*. Smafan. Retrieved July 20, 2020 from <https://smafan.com/blogs/smart-home/our-ceiling-fan-maintenance-tips>
- Chang, W. S. (2015). Reinforcement of timber columns and shear walls - a review. *Construction and Building Materials*, 97, 14-24.
- Church Buildings Council. (2007). *Guidance note electrical wiring installations in churches* (ChurchCare, Issue).
- Coleman, B. (2020). *A proactive approach to tech gear maintenance*. Retrieved 20.8 from <https://www.churchproduction.com/education/summer-tech-maintenance-a-proactive-approach/>
- Common Bond. (1997). *Maintenance wooden roof trusses*.
- Coppedge, A. (2019). *Church AV : what you may not know about the house of worship market*. rAve Publications. Retrieved July 20, 2020 from <https://www.ravepubs.com/church-av-what-you-may-not-know-about-the-house-of-worship-market/>
- Corradi, M., Osofero, A. I., & Borri, A. (2019). Repair and reinforcement of historic timber structures with stainless steel - a review. *Metals*, 9(106), 1-23.
- Courtenay, L. (2006). Where roof meets wall: structural innovations and hammer-beam antecedents, 1150-1250. *Annals of the New York Academy of Sciences*, 441(1), 89-124.
- Crossman, M., & Simm, J. (2011). *Manual on the use of timber in coastal and river engineering*. ICE Publishing.
- Cruzan, R. (2009). *Manager's guide to preventive building maintenance* (1st ed.). River Publishers.
- David, A. (2017). *Greater efforts needed for popular mosques*. New Straits Times. Retrieved October 19, 2019 from <https://www.nst.com.my/news/nation/2017/10/289086/greater-preservation-efforts-needed-popular-mosques>

Preserving Heritage:

Anglican Churches of National Heritage

This book is a journey through time and space, through ornate arches and intricately carved pews, and through the hearts of those who have tirelessly ensured the conservation of these Anglican churches. It is a testament to the unwavering faith that binds communities and transcends the boundaries of time and culture. As the custodians of this cultural and spiritual legacy, it is with great pride and reverence that we present this book. It serves as an exploration of the intricate fusion of faith and heritage, offering a window into the soul of Malaysia. Through these pages, we invite you to embark on a journey of discovery, understanding, and appreciation for the monumental task of preserving our national heritage.

We are deeply grateful to the Malaysian Department of National Heritage, architects, custodians, conservators, historians, volunteers, and all those who have generously shared their knowledge and experiences to make this project possible. Without their dedication, this book would remain an unfulfilled dream. May the pages that follow inspire an enduring commitment to the maintenance and preservation of our National Heritage Anglican Churches, ensuring that they stand as timeless symbols of faith, culture, and history for generations to come.



**PENERBIT
UTHM**

